

Inspection Photos

Loc: 321584

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/26/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the wellsite location. This area is bare of vegetation and has not been reclaimed.



Inspection Photos



Photo 2. Facing toward the wellhead which has not produced for a very long time. There is no well sign posted at the wellhead. Previous CA not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321584 | Date: 3/26/2024

Inspection Photos



Photo 3. Facing southeast at the location. Unused areas of the location are not reclaimed and consists of undesirable weeds.



Inspection Photos



Photo 4. Southwest side of the location facing northeast. There is a pipeline cellar has been removed since previous inspection. The disturbed area will need to be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:321584 | Date: 3/26/2024