

Inspection Photos

Loc: 380338

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/26/2024

County: CHEYENNE



Inspection Photos



Photo 1. Facing northeast toward the wellsite location.



Inspection Photos



Photo 2. The well sign has been set back up at the wellhead..



Inspection Photos



Photo 3. Facing southwest at the location. There are areas at the location with no vegetation. It appears soils may be compacted or impacted preventing vegetation growth.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380338 | Date: 3/26/2024

Inspection Photos



Photo 4. Northeast guyline anchor facing southwest.



Inspection Photos



Photo 5. This area is approximately 80'x20' and has no vegetation and appears to have impacted soils...



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:380338 | Date: 3/26/2024

Inspection Photos



Photo 6. Southeast corner of the location facing northwest..

