

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 3/26/2024



Location Entrance – Photo #00081



Wellheads – Photo #00091

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 3/26/2024



Separators – Photo #00089



Tank Battery – Photo #00087

# Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 3/26/2024



Dehydrator – Photo #00082

Gas Meter – Photo #00092

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 3/26/2024



**Storage of Supplies/Equipment – Photo #00085**



**Unprotected Soil Stockpile – Photo #00084**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-67S96W/6SWNW

Location ID: 334977

Date: 3/26/2024



**Unprotected Soil Stockpile – Photo #00086**