

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31NWNE

Location ID: 335393

Date: 3/26/2024



Mar 26, 2024 at 12:25:19
Parachute CO 81635
United States



Mar 26, 2024 at 12:26:33
Parachute CO 81635
United States

Location Entrance – Photo #00105

Wellheads – Photo #00108

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31NWNE

Location ID: 335393

Date: 3/26/2024



Separators – Photo #00107



Tank Battery – Photo #00106




Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31NWNE

Location ID: 335393

Date: 3/26/2024



Tank Capacity Not Posted – Photo #00110



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources