

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SENW

Location ID: 335297

Date: 3/26/2024



Wellheads – Photo #00120



Separators – Photo #00123

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SE1W

Location ID: 335297

Date: 3/26/2024



Tank Battery – Photo #00124



Stored Equipment/Debris – Photo #00126

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SENW

Location ID: 335297

Date: 3/26/2024



Stored Equipment/Debris – Photo #00127



Stored Equipment/Debris – Photo #00128

Inspection Photos

Location Name: CAERUS PICEANCE LLC, PUCKETT-66S96W/31SENW

Location ID: 335297

Date: 3/26/2024



Open-Ended Line – Photo #00125