

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 3/26/2024



Location Entrance – Photo #00166

Wellheads – Photo #00167

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 3/26/2024



Mar 26, 2024 at 13:31:39



Mar 26, 2024 at 13:31:56

Separators – Photo #00170

Tank Battery – Photo #00171

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 3/26/2024



Open-Ended Load Line – Photo #00172



Insufficient Erosion Control – Photo #00169