

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/32SESW

Location ID: 323881

Date: 3/26/2024



Wellhead – Photo #00180



Separator – Photo #00182

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/32SESW

Location ID: 323881

Date: 3/26/2024



Tank Battery – Photo #00185



Open-Ended Load Line – Photo #00186

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S96W/32SESW

Location ID: 323881

Date: 3/26/2024



Insufficient Erosion Control/Degradation – Photo #00183



Insufficient Erosion Control/Degradation – Photo #00184