

**Inspection Photos**  
**Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad**  
**Location # 334888**



**Photo # 1179 From entrance to location**



**Photo # 1180 Location**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888

Mar 25, 2024 at 10:52:37 AM



Photo # 1181 Location

Mar 25, 2024 at 10:53:27 AM



Photo # 1182 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888



Mar 25, 2024 at 10:53:48 AM

Photo # 1183 Location



Mar 25, 2024 at 11:01:22 AM

Photo # 1184 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888



Photo # 1185 Location




Photo # 1186 Location





## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888



Photo # 1187 Location



Photo # 1188 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888



Photo # 1189 Location



Photo # 1190 Location





## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888



Photo # 1191 Location



Photo # 1192 Debris

## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888



**Photo # 1193 Diesel tank missing some required information**



**Photo # 1194 Diesel tank missing some required information**



## Inspection Photos

Location Name: TEP Rocky Mountain LLC RMV 83-34 Pad

Location # 334888



**Photo # 1195 Methanol tank label weathered/damaged & some required information illegible.**



**Photo # 1196**

