

**Operator:** *Crestone Peak Resources*

**Location Name:** *ANDERSON TRUST C 62N68W 32NENE*

**Loc ID:** *322691*

**Inspection:** *714300041*



**Exhibit A**

**CA:** *A small excavation remains open at the location of the former tank battery. No groundwater was present in the excavation. No E&P waste stored on site. All tank battery equipment has been removed from the location. Form 27 Doc No 403678585 (In Process) lists the date of completion of remediation as 7/30/2024.v In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Operator will comply with the implementation schedule and Conditions of Approval for all remaining remediation of soil impacts, reclamation and reporting established in the ECMC Remediation Project No. 24140.*

**CA Resolution:** Waddle has been installed to comply with Rule 913.d.(1).