

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 3/28/2024



Mar 28, 2024 at 13:48:58
Parachute CO 81635
United States



Mar 28, 2024 at 13:49:57
Parachute CO 81635
United States

Location Entrance – Photo #00232

Wellheads – Photo #00235

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 3/28/2024



Separators – Photo #00233



Tank Battery – Photo #00234



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 3/28/2024



Insufficient Erosion Control – Photo #00236



Sediment Transport onto Location – Photo #00237

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-67S96W/1NWNW

Location ID: 334871

Date: 3/28/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00238