

Inspection Photos  
Location Name: Rainbow LC28-74-1HNA Production Facility  
Location ID: 422406



Energy and Carbon Management Commission  
40.71442, -103.98419, 4742.7ft  
03/27/2024 11:29:54



Energy and Carbon Management Commission  
40.71435, -103.98533, 4780.5ft  
03/27/2024 11:43:07

Photo 1 – Signs at Entrance

Photo 2 – Signs at Entrance

**Inspection Photos**  
**Location Name: Rainbow LC28-74-1HNA Production Facility**  
**Location ID: 422406**



**Photo 3 – Maintenance Tank**



**Photo 4 – Gas Meter Houses**



## Inspection Photos

Location Name: Rainbow LC28-74-1HNA Production Facility

Location ID: 422406



**Photo 5 – Gas Meter House**



**Photo 6 – Compressors**



**Inspection Photos**  
**Location Name: Rainbow LC28-74-1HNA Production Facility**  
**Location ID: 422406**




**Photo 7 – Risers at Rack Unmarked**



**Photo 8 – Risers at Rack Unmarked**



**Inspection Photos**  
**Location Name: Rainbow LC28-74-1HNA Production Facility**  
**Location ID: 422406**



**Photo 9 – Risers at Rack Unmarked**




**Photo 10 – South Separators**



**Inspection Photos**  
**Location Name: Rainbow LC28-74-1HNA Production Facility**  
**Location ID: 422406**




**Photo 11 – Risers at South Separators Unmarked**



**Photo 12 – Risers at South Separators Unmarked**



**Inspection Photos**  
**Location Name: Rainbow LC28-74-1HNA Production Facility**  
**Location ID: 422406**



**Photo 13 – Risers at South Separators Unmarked**



**Photo 14 – North Separators**

## Inspection Photos

Location Name: Rainbow LC28-74-1HNA Production Facility

Location ID: 422406



**Photo 15 – Heater Treater and Instrumental Air Unit**



**Photo 16 – Water Tanks**



## Inspection Photos

Location Name: Rainbow LC28-74-1HNA Production Facility

Location ID: 422406



**Photo 17 – Water ECD**



**Photo 18 – Crude Oil Tank ECDs**



## Inspection Photos

Location Name: Rainbow LC28-74-1HNA Production Facility

Location ID: 422406



Energy and Carbon Management Commission  
40.71588, -103.98586, 4790.6ft  
03/27/2024 11:39:57

**Photo 19 – VRU**



Energy and Carbon Management Commission  
40.71574, -103.98587, 4784.9ft  
03/27/2024 11:40:04

**Photo 20 – Crude Oil Tanks**



## Inspection Photos

Location Name: Rainbow LC28-74-1HNA Production Facility

Location ID: 422406



Energy and Carbon Management Commission  
40.7148, -103.98587, 4775.5ft  
03/27/2024 11:40:39

**Photo 21 – LACT Unit**



Energy and Carbon Management Commission  
40.71465, -103.98557, 4779.6ft  
03/27/2024 11:41:00

**Photo 22 – Crude Oil Tanks and LACT**




## Inspection Photos

Location Name: Rainbow LC28-74-1HNA Production Facility

Location ID: 422406



**Photo 23 – VRTs**



**Photo 24 – Unmarked Risers**