

Final Reclamation Inspection

March 28th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326108

Inspection Document #: 714000618

La Plata County, CO

Township: SWNW 30 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108

3/28/24
+37.073205,-107.989993
194° S



Photo 1. Overview of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108




Photo 2. View of russian thistle debris observed along the southern and western edges of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07486

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



Photo 3. Trash observed in the western interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07486

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



Photo 4. Unused oil and gas fitting equipment observed on location.



Inspection Photos

Location Name: Eldridge 30-01 1

Location ID: 326108



Photo 5. Additional unused oil and gas equipment observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07486

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



Photo 6. Produced water sign observed deteriorating and not displaying tank capacity.

Inspection Photos
Location Name: Eldridge 30-01 1
Location ID: 326108



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area comprised of sagebrush, crested wheatgrass, juniper and greasewood.

API #: 067-07486