

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Energy and Carbon Management Commission
40.7149, -104.00146, 4821.9ft
03/27/2024 11:58:15



Energy and Carbon Management Commission
40.7149, -104.00148, 4823.0ft
03/27/2024 11:58:20

Photo 1 – Maintenance Tank

Photo 2 – Gas Meters

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Photo 3 – Compressors

Photo 4 – Stained Soil

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818




Photo 5 – Wildlife Netting in disrepair



Photo 6 – Unmarked Riser at Rack

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818





Photo 7 – Knockouts

Photo 8 – Unmarked Risers at Rack

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Energy and Carbon Management Commission
40.71513, -104.00173, 4819.9ft
03/27/2024 12:00:47



Energy and Carbon Management Commission
40.71494, -104.00187, 4821.0ft
03/27/2024 12:01:18

Photo 9 – Unmarked Risers at Rack

Photo 8 – South Separators

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Photo 11 – Gas Meter Houses

Photo 12 – Unmarked Risers at Separators

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Photo 13 – North Separators

Photo 14 – Unmarked Risers at Separators

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Photo 15 – Unmarked Risers at Separators



Photo 16 – Heater Treater and Instrumental Air Unit

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Photo 17 – Unmarked Risers at Air Unit

Photo 18 – Unmarked Riser at Air Unit

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Photo 19 – VRTs



Photo 20 – Stained Soil at Water Tanks

Inspection Photos
Location Name: Rico LC29-74-1HNA-Production Facility
Location ID: 435818



Photo 21 – Water Tanks



Photo 22 – ECDs

Inspection Photos

Location Name: Rico LC29-74-1HNA-Production Facility

Location ID: 435818



Energy and Carbon Management Commission
40.71555, -104.00321, 4840.8ft
03/27/2024 12:07:25

Photo 23 – Crude Oil Tanks