

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Tank facility

Facility ID # 479723



Photo # 2043 From entrance to location



Photo # 2044 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Tank facility

Facility ID # 479723



Photo # 2045 Location



Photo # 2046 Location

Inspection Photos
Location Name: TEP Rocky Mountain LLC Juhan Tank facility
Facility ID # 479723



Photo # 2047 Location



Photo # 2048 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Tank facility

Facility ID # 479723



Photo # 2049 Location



Photo # 2050 Dead weeds/debris

Inspection Photos
Location Name: TEP Rocky Mountain LLC Juhan Tank facility
Facility ID # 479723



Photo # 2051 Dead weeds/debris



Photo # 2052 Dead weeds/debris

Inspection Photos

Location Name: TEP Rocky Mountain LLC Juhan Tank facility

Facility ID # 479723



Photo # 2053 Open ended load line