

Operator: EXTRACTION OIL & GAS INC

Location Name: Historic Miller 4-17J/Miller 14-17 Pit

Inspection: 714300039



Exhibit A

CA: Multiple soil stockpiles are present on location with no BMPs. No indication if the stockpiles are contaminated. Manage waste in compliance with Rule 913.b.iv and COGCC Guidance 913.b.(5)B i-v.

CA Resolution: Operator has appropriately installed signage noting that the stockpiles are not contaminated to comply with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v.