

**Inspection Photos**  
**Location Name: LC 11-16 Production Facility**  
**Location ID: 433936**



**Photo 1 – Separators**



**Photo 2 – Compressor**

**Inspection Photos**  
**Location Name: LC 11-16 Production Facility**  
**Location ID: 433936**



**Photo 3 – Instrumental Air Unit and Solar Panels**



**Photo 4 – Water Tanks**

**Inspection Photos**  
**Location Name: LC 11-16 Production Facility**  
**Location ID: 433936**



**Photo 5 – Crude Oil Tanks**



**Photo 6 – LACT Unit**



**Inspection Photos**  
**Location Name: LC 11-16 Production Facility**  
**Location ID: 433936**



**Photo 7 – ECDs**



**Photo 8 – VRT**

**Inspection Photos**  
**Location Name: LC 11-16 Production Facility**  
**Location ID: 433936**



**Photo 9 – Compressor**



**Photo 10 – Gas Meter Houses**

**Inspection Photos**  
**Location Name: LC 11-16 Production Facility**  
**Location ID: 433936**



**Photo 11 – Separators**



**Photo 12 – Maintenance Tank – NFPA and Content Labels**



Inspection Photos  
Location Name: LC 11-16 Production Facility  
Location ID: 433936



Energy and Carbon Management Commission  
40.75853, -103.94289, 4886.8ft  
03/29/2024 12:03:33

Photo 13 – Signs at Entrance