

Inspection Photos
Location Name: UPRR 23 PAN AM D 2
Location ID: 319939



Photo #1 Crud tank.



Photo #2 P/W tank.

Inspection Photos
Location Name: UPRR 23 PAN AM D 2
Location ID: 319939



Photo #3 Separator, meter & ECD.



Photo #4 Trash on location.

Inspection Photos
Location Name: UPRR 23 PAN AM D 2
Location ID: 319939



Photo #5 Pump jack.