

Inspection Photos
Location Name: Cleveland 2
Location ID: 332884



Energy & Carbon Management Commission
40.11106, -104.90316, 4985.6ft, 53°
04/02/2024 12:14:10



Energy & Carbon Management Commission
40.11104, -104.90291, 4972.9ft, 25°
04/02/2024 12:14:38

Photo 1 Location.

Photo 2 WH sign.

Inspection Photos
Location Name: Cleveland 2
Location ID: 332884



Photo 3 WH.



Photo 4 Unnecessary equipment.

Inspection Photos
Location Name: Cleveland 2
Location ID: 332884



Photo 5 Unnecessary equipment.



Photo 6 Unnecessary equipment.