

Inspection Photos
Location Name: Martin T. Hart 1
Location ID: 317639



Photo 1 Location.



Photo 2 Wellsite over run with dead vegetation.

Inspection Photos
Location Name: Martin T. Hart 1
Location ID: 317639



Photo 3 Dead vegetation around the PJ.

Photo 4 WH sign covered in Dead vegetation.

Inspection Photos
Location Name: Martin T. Hart 1
Location ID: 317639



Photo 5 WH.

Photo 6 Ancillary Equipment covered in dead vegetation.

Inspection Photos
Location Name: Martin T. Hart 1
Location ID: 317639



Photo 7 Ancillary Equipment covered in dead vegetation.