

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 4/2/2024



Apr 2, 2024 at 10:07:54



Apr 2, 2024 at 10:08:30

Location Entrance – Photo #00275

Wellhead/Weeds – Photo #00276

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 4/2/2024



Wellhead/Weeds – Photo #00278



Separator/Gas Meter/Weeds – Photo #00281

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 4/2/2024



Tank Battery/Weeds – Photo #00280



Tank Battery/Weeds – Photo #00283

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 4/2/2024



Storage of Unused Equipment/Weeds – Photo #00279



Lack of Stabilization/Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #00286

Inspection Photos

Location Name: VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE

Location ID: 334269

Date: 4/2/2024



Degraded Waddles on Perimeter of Location – Photo #00285