

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2024

Submitted Date:

04/03/2024

Document Number:

711900484

FIELD INSPECTION FORMLoc ID 313787 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10657

Name of Operator: PCR OPERATING LLC

Address: 9211 BROADWAY ST #17493

City: SAN ANTONIO State: TX Zip: 78217

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Quint, Craig		craig.quint@state.co.us	
Wehrer, Gene		gwehrer1961@outlook.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
225146	WELL	SI	04/01/2020	ERIW	087-05544	ADENA J SAND UNIT W-33	SI

General Comment:

UIC ROUTINE 2024 - LAST MIT 4-22-2021 - WELL TA OVER (2) YRS.

Location

Lease Road:			
Type	Access		
comment:	TWO TRACK GRASSLAND - MAINTAIN LEASE ROAD		
Corrective Action:		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	REPLACE STICKER ON SIGN		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	REPLACE STICKER ON SIGN		Date:
Corrective Action:			

Good Housekeeping:			
Type	OTHER		
Comment:	CONTROL VEGETATION AT WELLHEAD		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: NONE

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	NO CHANGE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 225146 Type: WELL API Number: 087-05544 Status: SI Insp. Status: SI

Underground Injection Control

UIC Violation: Maximum Injection Pressure:

UIC Routine

Inj./Tube: Pressure or inches of Hg 0 Previous Test Pressure MPP
(e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg 0 Previous Test Pressure Last MIT: 04/22/2021

Brhd: Pressure or inches of Hg Previous Test Pressure AnnMTReq:

Comment: UIC ROUTINE 2024 - NO PRESSURE ON WELL

Corrective Action: Date:

Method of Injection:

Test Type: Tbg psi: Csg psi: BH psi:

Insp. Status:

Comment:

Corrective Action: Date:

COGCC Comments

Comment	User	Date
UIC ROUTINE 2024	schureky	04/03/2024