

Inspection Photos
Location Name: Marcus State W 36-06JI
Location ID: 332434



Photo 1 Location.



Photo 2 WH sign.

Inspection Photos
Location Name: Marcus State W 36-06JI
Location ID: 332434



Photo 3 WH is SI/LOTO.



Photo 4 Tank battery location.

Inspection Photos
Location Name: Marcus State W 36-06JI
Location ID: 332434



Photo 5 Gas meter Run is SI/LOTO.



Photo 6 Horizontal Heated Separator is SI/LOTO.

Inspection Photos
Location Name: Marcus State W 36-06J
Location ID: 332434



Photo 7 TB sign.



Photo 8 Tank Battery is SI/LOTO.

