

Inspection Photos

Location Name: TEP Rocky Mountain LLC WEBSTER HILL/HEATH RMV 234-28 Pad

Location # 324164



Photo # 2335 From entrance to location



Photo # 2336 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WEBSTER HILL/HEATH RMV 234-28 Pad

Location # 324164



Photo # 2337 Location



Photo # 2338 Location



Inspection Photos

Location Name: TEP Rocky Mountain LLC WEBSTER HILL/HEATH RMV 234-28 Pad

Location # 324164



Photo # 2339 Location



Photo # 2340 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WEBSTER HILL/HEATH RMV 234-28 Pad

Location # 324164



Photo # 2341 Location



Photo # 2342 Netting/wildlife BMP needs maintenance

Inspection Photos

Location Name: TEP Rocky Mountain LLC WEBSTER HILL/HEATH RMV 234-28 Pad

Location # 324164



Photo # 2343 Netting/wildlife BMP needs maintenance



Photo # 2344 Open ended load line