

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403741410

Date Received:  
04/03/2024

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 714000411

Inspection Date: 02/13/2024

FIR Submit Date: 02/14/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 333970

Location Name: BLACK GAS UNIT 21-22-M34N8W Number: 22SENE County: \_\_\_\_\_

Qtrqtr: SENE Sec: 22 Twp: 34N Range: 8W Meridian: M

Latitude: 37.179521 Longitude: -107.699574

### FACILITY - API Number: 05-067-00 Facility ID: 333970

Facility Name: BLACK GAS UNIT 21-22-M34N8W Number: 22SENE

Qtrqtr: SENE Sec: 22 Twp: 34N Range: 8W Meridian: M

Latitude: 37.179521 Longitude: -107.699574

### CORRECTIVE ACTIONS:

**2**  CA# 192043

Corrective Action: Comply with rule 606.

Date: 02/29/2024

Response: CA COMPLETED

Date of Completion: 03/29/2024

Operator Comment: Unused equipment removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

3  CA# 192044

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002

Date: 02/19/2024

Response: CA COMPLETED

Date of Completion: 03/29/2024

Operator Comment: Wellhead cleaned up and impacted surface material removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Partial CA completed. See attached completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley

Signed:

Title: Permitting Specialist I

Date: 4/3/2024 12:58:25 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403741410	FIR RESOLUTION SUBMITTED
403741418	Black 21-22 2&4; Partial CA completion photos

Total Attach: 2 Files