

Inspection Photos
Location Name: Timbro LC 13-72HN
Location ID: 421834



Photo 1 – Tank Battery



Photo 2 – ECD

Inspection Photos
Location Name: Timbro LC 13-72HN
Location ID: 421834



Photo 3 – Separators



Photo 4 – Wellhead Sign

Inspection Photos
Location Name: Timbro LC 13-72HN
Location ID: 421834



Photo 5 – Wellhead



Photo 6 – Stained Soil at Compressor

Inspection Photos
Location Name: Timbro LC 13-72HN
Location ID: 421834



Photo 7 – Stained Soil



Photo 8 – Gas Meters

Inspection Photos
Location Name: Ptasnik Federal LC 20-75HN
Location ID: 422561



Photo 9 – VRU



Photo 10 – Tank Battery

Inspection Photos
Location Name: Timbro LC 13-72HN
Location ID: 421834



Energy and Carbon Management Commission
40.74402, -103.91868, 4790.8ft
04/03/2024 13:15:02

Photo 11 – Tank Battery Sign