

Interim Reclamation and Stormwater Inspection

March 22, 2024

Operator: KP Kauffman Company INC # 46290

Location ID: 320769

Inspection Document #: 709400986

Arapahoe County, CO

NENW Section 32 T4S R63W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Sierra-Mitchell #32-5

Location ID: 320769



Photo 1. Photo taken facing north of location sign



Photo 2. Photo taken facing north of weeds (kochia & russian thistle) around wellhead/pumpjack and on site.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400986

Inspection Photos
Location Name: Sierra-Mitchell #32-5
Location ID: 320769



Photo 3. Photo taken facing north of open excavation and cut and capped well, lacking exclusionary fencing.



Photo 4. Photo taken facing west of excavation from flowline removal onsite, lacking exclusionary fencing.

Inspection Photos
Location Name: Sierra-Mitchell #32-5
Location ID: 320769



Photo 5. Photo taken facing north of open excavation, lacking exclusionary fencing.



Photo 6. Photo taken facing northwest of open excavation and cut and capped well, lacking proper exclusionary fencing.

Inspection Photos

Location Name: Sierra-Mitchell #32-5

Location ID: 320769




Photo 7. Photo taken facing west of open excavation, lacking exclusionary fencing.



Photo 8. Photo taken facing southwest of harvested wheat field off site.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400986

Inspection Photos

Location Name: Sierra-Mitchell #32-5

Location ID: 320769



Photo 9. Photo taken facing southeast of harvested wheat field off site.

Photo 10. Photo taken facing west of open excavation, lacking proper exclusionary fencing.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Number: 709400986

Inspection Photos
Location Name: Sierra-Mitchell #32-5
Location ID: 320769



Photo 11. Photo taken facing east of contaminated sign posted on stockpile of soil on site.



Photo 12. Photo taken facing southeast of contaminated soil stockpile on site.