

Caerus Piceance LLC
Willow Ridge Comm. T63X-2G
Location ID: 316372



Location entrance sign at access road entrance. If replaced additional information is required.



Location entrance. Update if replaced.

Caerus Piceance LLC
Willow Ridge Comm. T63X-2G
Location ID: 316372



Well sign missing required information



Open to wildlife

Caerus Piceance LLC
Willow Ridge Comm. T63X-2G
Location ID: 316372



Unused equipment



Unused equipment

Caerus Piceance LLC
Willow Ridge Comm. T63X-2G
Location ID: 316372



Unmarked anchor (SW)



Unmarked anchor (NW)

Caerus Piceance LLC
Willow Ridge Comm. T63X-2G
Location ID: 316372



Unmarked anchor (NE)



Relief riser missing rain protection

Caerus Piceance LLC
Willow Ridge Comm. T63X-2G
Location ID: 316372



No visible display of gas meter calibration

Location from Northeast corner

**Caerus Piceance LLC
Willow Ridge Comm. T63X-2G
Location ID: 316372**



Location from Northwest corner



Location from Southeast corner