

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 2910 From entrance to location



Photo # 2911 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 2912 Location



Photo # 2913 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 2914 Location



Photo # 2915 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 2916 Location




Photo # 2917 Location

Inspection Photos

Location Name: TEP Rocky Mountain LLC WATSON RANCH A Pad

Location # 413055



Photo # 2918 Mechanical condition – chemical tank leaking fluid



Photo # 2919 Mechanical condition – chemical tank leaking fluid