

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 424426



Photo 1 Location.



Photo 2 LACT.

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 424426



Photo 3 TB signs.



Photo 4 TB, VRT.

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 424426



Photo 5 VRU.



Photo 6 Ancillary equip.

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 424426



Photo 7 ECDs.



Photo 8 Vertical Separator.

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 424426



Photo 9 .



Photo 10 Horizontal Heated Separator.

Inspection Photos
Location Name: Gobbler Tank Battery 1C-23HZ
Location ID: 424426



Photo 11 Horizontal Heated Separator.



Photo 12 Gas Meter Run x 2 cards indicate current calibration.