

Interim Reclamation and Stormwater Inspection

Date: 4/2/24

Operator: PDC Energy Inc - 69175

Location ID: 457498

Inspection Document #: 713900500

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Ridgway 3N66W1 1-6
Location ID: 457498



Photo 1. The photo was taken at the entrance to the well location facing South. The photo illustrates the operator signage.



Photo 2. The photo was taken at the well location facing West. The photo illustrates the wellheads.

Inspection Photos
Location Name: Ridgway 3N66W1 1-6
Location ID: 457498



Photo 3. The photo was taken at the well location facing Southwest. The photo illustrates the unused equipment left on the production pad.

Photo 4. The photo was taken at the well location facing West. The photo illustrates unmanaged Kochia along the Northwest berm along the production pad.

Inspection Photos

Location Name: Ridgway 3N66W1 1-6

Location ID: 457498



Photo 5. The photo was taken at the well location facing Northeast. The photo illustrates unused equipment being stored on the production pad.

Photo 6. The photo was taken at the well location facing Southeast. The photo illustrates interim areas are still too early in the season to evaluate growth.