

Interim Reclamation and Stormwater Inspection

Date: 4/2/24

Operator: PDC Energy Inc - 69175

Location ID: 426929

Inspection Document #: 713900505

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Roy K 25-64-1HN
Location ID: 426929



Photo 1. The photo was taken at the entrance to the well location facing Northwest. The photo illustrates the access road and operator sign.

Photo 2. The photo was taken at the well location facing Southwest. The photo illustrates wellhead panels that have been piled during mowing activities.

Note - Talking with the operator personnel on location the panels are planned to be put back in place ASAP.

Inspection Photos
Location Name: Roy K 25-64-1HN
Location ID: 426929



Photo 3. The photo was taken at the well location facing East. The photo illustrates the two track between the wellheads and production facility. The interim area around the wellheads has been mowed.

Photo 4. The photo was taken at the well location facing East. The photo illustrates the wellheads and the area where the panels were removed for mowing.

Inspection Photos
Location Name: Roy K 25-64-1HN
Location ID: 426929



Photo 5. The photo was taken at the well location facing Southwest. The photo illustrates the tank batteries with rain water from a previous storm.



Photo 6. The photo was taken at the well location facing Southeast. The photo illustrates facility equipment.

Inspection Photos
Location Name: Roy K 25-64-1HN
Location ID: 426929



Photo 7. The photo was taken at the well location facing North. The photo illustrates mowed interim areas.