

Interim Reclamation and Stormwater Inspection

Date: 4/2/24

Operator: PDC Energy Inc - 69175

Location ID: 426298

Inspection Document #: 713900509

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Schmidt G30-65HN Tank
Location ID: 426298



Photo 1. The photo was taken at the entrance to the well location facing Southwest. The photo illustrates the access road and cattle guard.



Photo 2. The photo was taken at the well location facing South. The photo illustrates the operator signage.

Inspection Photos

Location Name: Schmidt G30-65HN Tank

Location ID: 426298



Photo 3. The photo was taken at the well location facing North. The photo illustrates unused equipment being stored on the production pad.



Photo 4. The photo was taken at the well location facing Southeast. The photo illustrates a broken tank stored on the production pad.