

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/28SWSE

Location ID: 324185

Date: 4/4/2024



Wellhead – Photo #00333



Separator – Photo #00335



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/28SWSE

Location ID: 324185

Date: 4/4/2024



Unprotected Soil Stockpile – Photo #00334



Unprotected Soil Stockpile Along Access Road– Photo #00336