

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 4/4/2024



**Location Entrance – Photo #00344**



**Wellheads – Photo #00345**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 4/4/2024



Separators – Photo #00350



Dehydrator/Chem Tanks – Photo #00351



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 4/4/2024



**Tank Battery/Chem Tank – Photo #00346**



**Wildlife Entry Hazard – Photo #00349**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 4/4/2024



**Unsecured Separator – Photo #00352**





## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 4/4/2024



Lack of Stabilization – Photo #00353



Lack of Stabilization – Photo #00354



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Riley/1

Location ID: 335013

Date: 4/4/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit  
– Photo #00356**



**Degradation/Transportation of Sediment – Photo #00355**