

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL/MV 60-8D

Location ID: 334950

Date: 4/4/2024



Location Entrance – Photo #00357



Wellheads – Photo #00358

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL/MV 60-8D

Location ID: 334950

Date: 4/4/2024



Separators – Photo #00360



Tank Battery – Photo #00362

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL/MV 60-8D

Location ID: 334950

Date: 4/4/2024



Lack of Stabilization – Photo #00361



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #00363**