

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC Rulison Compressor Station
Location # 466236



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to NSO Habitat area. Location is approximately 317 yards
from Spruce creek.**

Section/Township/Range: 8 7S94W



Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC Rulison Compressor Station
Location # 466236



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC Rulison Compressor Station
Location # 466236



**Photo # 2663 Chemical tank lacks containment/BMP
(chemical tank is not labeled & is approximately half full of
unknown fluid)**



**Photo # 2664 Chemical tank lacks containment/BMP
(chemical tank is not labeled & is approximately half full of
unknown fluid)**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC Rulison Compressor Station
Location # 466236



Photo # 2665 Drain/BMP needs maintenance/drain clogged with sediment (drain is near NW corner of location)



Photo # 2666 Drain/BMP needs maintenance/drain clogged with sediment (drain is near NW corner of location)

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC Rulison Compressor Station
Location # 466236



Photo # 2667 Erosion & transport of sediment off location into a vegetated area/sediment choking off vegetation /insufficient BMP's



Photo # 2668 Erosion & transport of sediment off location into a vegetated area/sediment choking off vegetation /insufficient BMP's

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC Rulison Compressor Station
Location # 466236



Apr 3, 2024 at 1:06:48 PM
CO

**Photo # 2669 Erosion & transport of sediment off location
into a vegetated area/sediment choking off vegetation
/insufficient BMP's**

