



99999999

**RADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT****SATISFACTORY INSPECTION**1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100☒ **NOTICE OF SATISFACTORY INSPECTION**

API No. 05-

123 - 7086

LEASE NAME:

Gov- #1

LOCATION:

SE NW 8-9N-56W

OPERATOR:

Chancellor

DATE:

2-14-97

INSPECTOR:

EBB

Ins. Type: HR

Ins. Status: DA

PA: Y

N

Prog/Fail: P

F

Viol.: Y

N

NOV: Y

N

INSPECTION ITEM**COMMENTS****INPUT****Well ID Signs**

(Rule 210, 604.c(4))

Bond RELEASE Plugged 5-21-97

Pits (Reserve/Production)

(Rule 902, 903, 904, 905)

Fences

(Rule 603.b.7, 604.C.(3), 1002.A)

Tank Battery Equipment

(Rule 603.b.3, 604)

Fire Walls/Berns/Dikes

(Rule 603.b.12, 604)

BEST IMAGE
AVAILABLE**General Housekeeping**

(Rule 603)

Spills (Oil/Water)

(Rule 907)

Bradenhead

(Rule 207.b)

Drilling Well/Workover

(Rule 317)

Surface Rehabilitation

(Rule 1002, 1003, 1004, 1103)

grassland

Miscellaneous

RECEIVED

MAR 13 1997

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:



00265036

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.