

# Inspection Photos

04/04/2023

**Operator:** CAERUS PICEANCE LLC - 10456

**Location ID:** 312549

**Inspection Doc:** 696205716

Mesa County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312549



April 4, 2024



April 4, 2024

**Photo 1:** Photos 1-2 taken from the central areas of the Location. Photos provide an overview of the Reclamation from north, east, south to west. Location meets ECMC 1004 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



## Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312549



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 312549



**Photo 3:** Photo taken from the former access road/stream crossing.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources