

Inspection Photos

04/04/2023

Operator: KOCH EXPLORATION COMPANY LLC
#49100

Location ID: 391071

Inspection Doc: 696205720

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC #49100

Location ID: 391071



Photo 1: Photos 1-2 provide an overview of the Location from north, east, south and west. Vegetation on Location is progressing towards 1004 standards, though weed species are still dominant throughout the disturbance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC #49100

Location ID: 391071



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: KOCH EXPLORATION COMPANY LLC #49100

Location ID: 391071



Photo 3: Photo example showing perimeter fence installed along perimeter of the disturbance.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources