

# Final Reclamation Inspection

April 3rd, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 311923

Inspection Document #: 714000630

La Plata County, CO

Township: NWNE 19 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Mcelvain Harmon 1A  
Location ID: 311923



4/3/24  
+37.093870,-107.755368  
277° W



4/3/24  
+37.093949,-107.755594  
332° NW

Photo 1. Overview of the disturbance taken from the access point facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08193



Inspection Photos  
Location Name: Mcelvain Harmon 1A  
Location ID: 311923



**Photo 2.** Evidence of sediment transport and erosion observed on location.  
Additional stabilization is needed.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-08193



Inspection Photos  
Location Name: Mcelvain Harmon 1A  
Location ID: 311923



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Woody plank debris/trash observed on location.

API #: 067-08193