

Final Reclamation Inspection

April 3rd, 2024

Operator: Rim Operating Inc - 74650

Location ID: 306973

Inspection Document #: 714000632

La Plata County, CO

Township: NWSE 20 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bullseye 2
Location ID: 306973

4/3/24
+37.086490,-107.738186
291° W



Photo 1. Overview of the well pad disturbance the access point facing center.



API #: 067-09286

Inspection Photos
Location Name: Bullseye 2
Location ID: 306973

4/3/24
+37.086474,-107.738556
217° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of southern interim reclamation area facing southwest.
Vegetation comprised of smooth brome and rabbitbrush.

API #: 067-09286

Inspection Photos
Location Name: Bullseye 2
Location ID: 306973



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Gully erosion identified in the previous inspection doc #693904604 has been addressed/resolved.

API #: 067-09286

Inspection Photos
Location Name: Bullseye 2
Location ID: 306973



4/3/24
+37.086397, -107.738348
252° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Stained soil corrective action identified in the previous inspection doc #693904604 has been addressed/resolved.

API #: 067-09286

Inspection Photos
Location Name: Bullseye 2
Location ID: 306973



4/3/24
+37.086799,-107.738798
192° S

Photo 5. Rutting observed site wide. Additional stabilization is needed to minimize site degradation.



Inspection Photos
Location Name: Bullseye 2
Location ID: 306973



Photo 6. Unused wood pallet and culvert tubing observed stored within the produced water tanks berm.

Inspection Photos
Location Name: Bullseye 2
Location ID: 306973



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. View of the reference area comprised of smooth brome, gambel oak and juniper.

API #: 067-09286