

Final Reclamation Inspection

April 5th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 333765

Inspection Document #: 714000637

La Plata County, CO

Township: SWSW 7 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**


Department of Natural Resources

Inspection Photos
Location Name: IGW 121
Location ID: 333765

4/5/24
+37.114118,-107.764822
268° W



Photo 1. Overview of the well pad disturbance the access point facing center.



API #: 067-09380

Inspection Photos
Location Name: IGW 121
Location ID: 333765



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of weedy russian thistle debris in the northeast corner of the disturbance.

API #: 067-09380

Inspection Photos
Location Name: IGW 121
Location ID: 333765




Photo 3. View of failing storm water BMPs and gully erosion forming in the northwest corner of the disturbance. Maintenance is needed in this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-09380

Inspection Photos
Location Name: IGW 121
Location ID: 333765



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Impacted surface material observed at the mump jack muffler.

API #: 067-09380

Inspection Photos
Location Name: IGW 121
Location ID: 333765



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of smooth brome, rabbit brush and sagebrush.

API #: 067-09380