

Final Reclamation Inspection

April 5th, 2024

Operator: Advanced Wireless Communications
LLC - 10737

Location ID: 333801

Inspection Document #: 714000638

La Plata County, CO

Township: NENE 18 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Slugger 1, 11
Location ID: 333801

4/5/24
+37.108074,-107.754233
174° S



Photo 1. Overview of the well pad disturbance the access point facing center.
Note: disturbance is shared with Arkoma Operations LLC.

Inspection Photos
Location Name: Slugger 1, 11
Location ID: 333801



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Stained surface material observed at Advanced Wireless Communications pump jack.

API #: 067-08985, 09751

Inspection Photos
Location Name: Slugger 1, 11
Location ID: 333801



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Weedy russian thistle debris observed at Advanced Wireless Communications produced water tank.

API #: 067-08985, 09751

Inspection Photos
Location Name: Slugger 1, 11
Location ID: 333801



Photo 4. Rutting observed throughout the disturbance. Additional stabilization is needed to minimize site degradation. As this is shared disturbance both operators will be receiving a corrective action.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08985, 09751

Inspection Photos
Location Name: Slugger 1, 11
Location ID: 333801



4/5/24
+37.107770,-107.753698
136° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of smooth brome, sage brush and juniper.

API #: 067-08985, 09751