


Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RWF 13-4 Pad

Location ID: 334720



Apr 4, 2024 at 3:23:06 PM
CO



Apr 4, 2024 at 3:24:27 PM
CO

Photo # 2818 From entrance to location

Photo # 2819 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RWF 13-4 Pad

Location ID: 334720



Photo # 2820 Location



Photo # 2821 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RWF 13-4 Pad

Location ID: 334720



Photo # 2822 Location




Photo # 2823 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RWF 13-4 Pad

Location ID: 334720



Photo # 2824 Netting/wildlife protection needs maintenance



Photo # 2825 Netting/wildlife protection needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RWF 13-4 Pad

Location ID: 334720



Photo # 2826 Debris



Photo # 2827 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BERNKLAU RWF 13-4 Pad

Location ID: 334720



Photo # 2828 Debris




Photo # 2829 Hog panels need maintenance