

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403701543

Date Received:
02/28/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		rbucogccinspectionreports@chevron.onmicrosoft.com
<u>Jenkins, Steve</u>		steve.jenkins@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 696305797

Inspection Date: 01/18/2024

FIR Submit Date: 01/18/2024

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 428526

Location Name: WELLS RANCH USX AE Number: 29-62-1HN County: _____

Qtrqtr: SWS Sec: 29 Twp: 6N Range: 62W Meridian: 6
W

Latitude: 40.451890 Longitude: -104.354550

FACILITY - API Number: 05-123-00 Facility ID: 428526

Facility Name: WELLS RANCH USX AE Number: 29-62-1HN

Qtrqtr: SWS Sec: 29 Twp: 6N Range: 62W Meridian: 6
W

Latitude: 40.451890 Longitude: -104.354550

CORRECTIVE ACTIONS:

1 CA# 191143

Corrective Action:

Date: 02/02/2024

Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well. All access roads to plugged and abandoned wells and associated production facilities shall be closed, graded and recontoured. Per Rule 1004.a

Form 6, Subsequent Report of Abandonment.
Within 30 days after abandonment, the Form 6, Well Abandonment Report – Subsequent Report of Abandonment will be filed with the Director. Per Rule 435.b (1)

Response: CA COMPLETED

Date of Completion: 02/28/2024

Operator
Comment:

- From 42 Start of Plugging Submitted under Doc Number 403669695
- Well was scheduled to be Cut/Capped 1/24/2024, but due to pressure issues has been added to the problem well list while the issue is mitigated.
- Form 6 Subsequent will be submitted 30 days after plugging operation is complete. Plugging Operations are deemed complete once the Cut/Cap of the Well has been completed.
- All surface equipment will be removed within 90 days of Plugging Operations being completed. Plugging Operations are deemed complete once the Cut/Cap of the Well has been completed.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved Pending Re-Inspection

OPERATOR COMMENT AND SUBMITTAL

Comment:

- From 42 Start of Plugging Submitted under Doc Number 403669695
- Well was scheduled to be Cut/Capped 1/24/2024, but due to pressure issues has been added to the problem well list while the issue is mitigated.
- Form 6 Subsequent will be submitted 30 days after plugging operation is complete. Plugging Operations are deemed complete once the Cut/Cap of the Well has been completed.
- All surface equipment will be removed within 90 days of Plugging Operations being completed. Plugging Operations are deemed complete once the Cut/Cap of the Well has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Javier Pellacani

Signed: _____

Title: HSE

Date: 2/28/2024 7:39:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403701543	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files