

Final Reclamation Inspection

April 5th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 311902

Inspection Document #: 714000647

La Plata County, CO

Township: SWSW 7 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FW Terrell 1A
Location ID: 311902



4/5/24
+37.113664,-107.764808
248° W

Photo 1. Overview of the well pad disturbance the access point facing center.



4/5/24
+37.113742,-107.765025
242° SW

Inspection Photos
Location Name: FW Terrell 1A
Location ID: 311902



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the western interim reclamation area facing southwest.
Vegetation comprised of smooth brome and rabbit brush.

API #: 067-08184

Inspection Photos
Location Name: FW Terrell 1A
Location ID: 311902



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area comprised of sagebrush, rabbit brush and smooth brome.

API #: 067-08184