

Final Reclamation Inspection

April 5th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 311924

Inspection Document #: 714000649

La Plata County, CO

Township: SESE 8 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ige 127, Olson Smith GU 2
Location ID: 311924



4/5/24
+37.114292,-107.744802
260° W



4/5/24
+37.114619,-107.735372
105° E



4/5/24
+37.114619,-107.735372
186° S

Photo 1. Overview of the well pad disturbance the access point facing center.

Inspection Photos

Location Name: Ige 127, Olson Smith GU 2

Location ID: 311924



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the eastern interim reclamation area facing north. Vegetation comprised of smooth brome, crested wheatgrass and rabbitbrush.

API #: 067-07911, 09545

Inspection Photos

Location Name: Ige 127, Olson Smith GU 2

Location ID: 311924



Photo 3. Wattle BMPs in the northeast corner of the disturbance area no longer functioning and need maintenance. Rill erosion forming below installed wattles.

Inspection Photos

Location Name: Ige 127, Olson Smith GU 2

Location ID: 311924



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Unused equipment corrective action identified in the previous inspection doc #702500775 has been addressed/resolved.

API #: 067-07911, 09545

Inspection Photos
Location Name: Ige 127, Olson Smith GU 2
Location ID: 311924



Photo 5. Weed corrective action identified in the previous inspection doc #702500775 has been addressed/resolved.



Inspection Photos
Location Name: Ige 127, Olson Smith GU 2
Location ID: 311924



Photo 6. Impacted surface material corrective action identified in the previous inspection doc #702500775 has been addressed/resolved.



Inspection Photos
Location Name: Ige 127, Olson Smith GU 2
Location ID: 311924



4/5/24
+37.114706,-107.735748
242° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area comprised of crested wheatgrass and sagebrush.

API #: 067-07911, 09545