

Final Reclamation Inspection

April 5th, 2024

Operator: SG Interests LTD - 77330

Location ID: 385360

Inspection Document #: 714000650

La Plata County, CO

Township: NENE 17 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Harmon 1
Location ID: 385360



4/5/24
+37.108966,-107.735438
156° SE

Photo 1. Overview of the well pad disturbance the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05426

Inspection Photos
Location Name: Harmon 1
Location ID: 385360



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

API #: 067-05426

Inspection Photos
Location Name: Harmon 1
Location ID: 385360



Photo 3. Cardinal photos taken from the center of the disturbance. Left photo facing south, right photo facing west. Note: minimal vegetation establishment observed at the disturbance. Revegetation was unsuccessful and additional reclamation/seeding is needed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-05426

Inspection Photos
Location Name: Harmon 1
Location ID: 385360



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Evidence of successful progressing revegetation observed on the western edge of the disturbance.

API #: 067-05426

Inspection Photos
Location Name: Harmon 1
Location ID: 385360



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Rill erosion observed at the well head marker. Additional stabilization/storm water BMPs are needed in this area.

API #: 067-05426

Inspection Photos
Location Name: Harmon 1
Location ID: 385360



Inspection Photos
Location Name: Harmon 1
Location ID: 385360



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area comprised of smooth brome and sagebrush.

API #: 067-05426