

# Final Reclamation Inspection

April 5th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 325156

Inspection Document #: 714000651

La Plata County, CO

Township: SESE 9 33N 8W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ford Olson Unit 1  
Location ID: 325156



4/5/24  
+37.114644,-107.718016  
299° NW

CAUTION  
NO SMOKING  
OR OPEN FLAME



4/5/24  
+37.116246,-107.720137  
334° NW

Photo 1. Overview of the well pad disturbance from the access point facing center.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-05464



Inspection Photos  
Location Name: Ford Olson Unit 1  
Location ID: 325156



**Photo 2.** Rutting observed site wie. Additional stabilization is needed to minimize site degradation.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-05464



Inspection Photos  
Location Name: Ford Olson Unit 1  
Location ID: 325156



**Photo 3.** Stormwater corrective action identified in the previous inspection doc #712700800 have been addressed/resolved.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-05464



Inspection Photos  
Location Name: Ford Olson Unit 1  
Location ID: 325156



**Photo 4.** Weedy russian thistle debris observed lining the western edge of the disturbance.



COLORADO  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 067-05464



Inspection Photos  
Location Name: Ford Olson Unit 1  
Location ID: 325156



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area comprised of smooth brome and sage brush.

API #: 067-05464