

Final Reclamation Inspection

April 5th, 2024

Operator: Arkoma Operations LLC - 10766

Location ID: 311911

Inspection Document #: 714000652

La Plata County, CO

Township: SESW 15 33N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hahn-N33N8W 15SESW
Location ID: 311911



Photo 1. Overview of the well pad disturbance from the access point facing center.

Inspection Photos
Location Name: Hahn-N33N8W 15SESW
Location ID: 311911



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of the northern interim reclamation area facing west.
Vegetation comprised of smooth brome and rabbit brush.

API #: 067-08112, 09022,
09346

Inspection Photos
Location Name: Hahn-N33N8W 15SESW
Location ID: 311911



Photo 3. View of stormwater BMPs in the western portion of the disturbance that are no longer functioning. Maintenance required in this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-08112, 09022,
09346

Inspection Photos

Location Name: Hahn-N33N8W 15SESW

Location ID: 311911



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Weedy kochia debris observed piling up in the northwest corner of the disturbance.

API #: 067-08112, 09022,
09346